



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY
GPS Testing
ACC GPS 11-07
April 28, 2011 – May 13, 2011
Wendover, UT

GPS testing scheduled as follows may result in unreliable or unavailable GPS signal.

A. Location: Centered at 402602N/1132936W or the BVL VOR 145.44 degree radial at 21.3NM.

B. Dates and times:

28 APR – 29 APR	1700Z – 2000Z	2200Z – 0000Z
30 APR - 06 MAY	1700Z – 2000Z	
09 MAY – 13 MAY	1700Z – 2000Z	

C. Duration: Tests will be conducted continuously during times requested above.

D. During testing, the GPS signal may be unreliable or unavailable within a 395NMR centered at 402602N/1132936W or the BVL VOR 145.44 degree radial at 21.3NM at FL400 and above, decreasing in area with decrease in altitude to 355NMR at FL250, 260NMR at 10,000 FT MSL, 265NMR at 4,000 FT AGL and 225NMR at 50 FT AGL.

E. Pilots are strongly encouraged to report anomalies during testing to the appropriate ARTCC to assist in the determination of the extent of GPS degradation during tests.

The NOTAMs discussed in this advisory may change with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

