LOPEZ

FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99′ W122°55.08′

SEATTLE

00 NOTAM FILE SEA

WATERWAY 05W-23W: 3000X150 (WATER)

WATERWAY 05W: Rgt tfc.

SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Beware of boats anchored in seaplane Idg area.

AIRPORT MANAGER: 360-468-4116 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04′ W122°56.26′

SFATTLE

209 B NOTAM FILE SEA

RWY16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N

RWY 16: REIL. PAPI(P2L)—GA 4.0° TCH 43 '. Trees. Rgt tfc.

RWY 34: REIL, PAPI(P2L)—GA 4.0° TCH 33', Trees.

AIRPORT REMARKS: Unattended. Rwy 16-34 soft shoulders and thids. AIRPORT MANAGER: 360-468-4116 COMMUNICATIONS: CTAF 128.25

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOST RIVER (See MAZAMA on page 250)

LOWER GRANITE STATE (See COLFAX on page 229)

LOWER MONUMENTAL STATE (See KAHLOTUS on page 244)

LYNDEN MUNI/JANSEN FLD (38W) 1 N UTC-8(-7DT) N48°57.35′ W122°27.49′

SEATTLE

B NOTAM FILE SEA 106

RWY 08-26: H2425X40 (ASPH) S-12 RWY LGTS(NSTD)

RWY 08: PAPI(P2L)—GA 3.0° TCH 15'. Thid dsplcd 262'. Trees.

RWY 26: PAPI(P2R)—GA 6.0° TCH 15'. Thid dsplcd 422'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 08-

LDA-2163

RWY 26: TORA-2425

LDA-2003

SERVICE: FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08–26 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Structures and trees in pri sfcs. Exposed ditch Rwy 08-26. Avoid night Indgs to Rwy 26-night Indgs should be performed on Rwy 08-winds permitting. 1850 ft btn thr lgts; Rwy 08 thr lgts located 134 ft prior to dsplcd thr. Rwy 08 thr relctd 155 ft for ngt opns; Rwy 26 thr relctd 434 ft for ngt opns; 1871 ft lgtd at night. No white/red lgts past dsplcd thld. Run-ups not permitted on Rwy 26 turn around taxiway. Acft with 40 ft wing span adzd to back taxi and not to use west twy. Fly PAPI on all approaches to Rwy 08. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.

AIRPORT MANAGER: 360-354-3446

COMMUNICATIONS: CTAF 122 9

VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560

COMM/NAV/WEATHER REMARKS: Automated UNICOM; 3 clicks.

MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56′ W119°38.22′

SEATTLE

2272 B NOTAM FILE SEA

RWY 03-21: H2575X46 (ASPH) LIRI

RWY 03: Road.

RWY 21 · Road

RUNWAY DECLARED DISTANCE INFORMATION

RWY 03: TORA-2400 RWY 21: TORA-2400

SERVICE: LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield. Bcn tempo OTS.

AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03-21 markings faded. Pilots bring own ropes. Lgtd wind tee.

AIRPORT MANAGER: 509-884-4700 COMMUNICATIONS: CTAF 122 9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MARTIN FLD (See COLLEGE PLACE on page 230)