176 ALASKA

## NAKNEK

NAKNEK (5NK) 1 N UTC-9(-8DT) N58°44.08′ W157°01.51′

70 NOTAM FILE ENA

RWY 08-26: 1950X50 (GRVL) RWY 08: Brush

RWY 26: Brush

RWY 14-32: 1836X45 (GRVL) 3.0% up SF

RWY 14: Brush. RWY 32: Brush.

SERVICE: S3 FUEL 100LL LGT Airport unlit.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Windsock unreliable. Acft on east side of Rwy 14-32 tied down in safety area. Road parallel to and 45' east of Rwy 32 centerline. Uncontrolled vehicular tfc on rwys. No line of sight between rwys or waterways. Float acft departing northwest lake to East, cross arpt at low alt. Acft not visible until airborne. Rwy 08-26 rocks exceeding 2" diameter and ruts 6". Rwy 08 slopes downhill to east. Rwy 14-32 rocks exceeding 2"-3" in diameter and 3" ruts. First 200 ' Rwy 32 soft when wet. First 400' Rwy 32 slopes downhill.

AIRPORT MANAGER: 907-246-3325 COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

258° 8.6 NM to fld. 95/16E. KING SALMON (H) VORTACW 112.8 AKN Chan 75 N58°43.48′ W156°45.14′

TACAN antenna offset 150' SE TACAN AZIMUTH unusable:

122°-142° blo 2,900°

122°-142° byd 15 NM

TACAN AZIMUTH & DME unusable:

335°-350° byd 35 NM blo 3,500°

COMM/NAV/WEATHER REMARKS: For a toll-free call to Kenai FSS dial 1-888-864-1737.

WATERWAY 08W-26W: 2000X300 (WATER)

SEAPLANE REMARKS: Unattended. E apch to lake over Rwy 14-32 Naknek arpt and Tibbetts arpt. Ramp. No line of sight between rwys or waterways. Rwy 08W-26W not on arpt property and is not owned or opr by the state of Alaska.

TIBBETTS (4AK9) PVT 0 SE UTC-9(-8DT) N58°44.06′ W157°00.43′

KODIAK

KODIAK

હ

**43** 

€3

C C

43

€3 43

€3 ¢ Ç

67

63

(C) (C)

€3

*~*3 €3

258° 8.6 NM

€3

From King Salmon "AKN" VORTAC

50 NOTAM FILE

RWY 16-34: 1700X60 (GRVL-DIRT)

RWY 16: Trees.

RWY 34: Wire.

SERVICE: S2

AIRPORT REMARKS: Attended daylight. Company equipment only. Spherical markers on power line in approach Rwy 34. Hump midway Rwy 16-34. Rwy soft during Spring thaw.

AIRPORT MANAGER: (907) 439-3853 COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: For a toll-free call to Kenai FSS dial 1-866-864-1737.

NANCY LAKE SPB (787) 0 NW UTC-9(-8DT) N61°42.20′ W150°00.43′ ANCHORAGE

214 NOTAM FILE ENA

WATERWAY N-S: 6000X600 (WATER)

SEAPLANE REMARKS: Unattended. No acft svcs avbl. Nancy Lake State Recreation Site has public access and camping facilities. Has dock, no dock mooring avbl but planes can heel-up away from public boat ramp and beach area. All other docks on lake are private.

AIRPORT MANAGER: 907-745-3975 COMMUNICATIONS: CTAF 122.8

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

NANWAK N60°23.12′ W166°12.86′ NOTAM FILE MYU.

(HW) SAB 323 AIX Chan 76 232° 1.8 NM to Mekoryuk. 38/13E.

BETHEL

L-3B

NDB/DME unusable:

115°-225° byd 30 NM RCO (KENAI RADIO)