


CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES  
 READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

NOTE: Due to distance of tower from transient ramp,  
 ATC unable to provide visual guidance or positioning  
 of aircraft. USE CAUTION.

ATIS 133.15  
 FLINT TOWER \* 126.3 257.9  
 GND CON 121.9  
 CLNC DEL 121.75  
 D

JANUARY 2025  
 ANNUAL RATE OF CHANGE  
 0.0° W



EC-1, 15 MAY 2025 to 12 JUN 2025

EC-1, 15 MAY 2025 to 12 JUN 2025