

BALTIMORE

MILLER FARM LANDING STRIP (7B4) 3 NE UTC-5(-4DT) N39°53.07' W82°35.34'

CINCINNATI

930 NOTAM FILE DAY

RWY 09-27: 3250X50 (TURF) LIRL(NSTD)

RWY 09: Thld dsplcd 270'. Crops.

RWY 27: Thld dsplcd 275'. Trees.

SERVICE: LGT Airport lighting available on request, contact arpt mgr. Rwy 09-27 NSTD LIRL; rwy ends lgtd with split red and green lgts; dsplcd thlds lgtd with 1 split red and green lgt each side of rwy.

AIRPORT REMARKS: Attended SR-SS. Dalgt hrs only. No student ops. Rwy 27 +6' to +13' brush/trees on rwy end 45' right to 125' right. Occasional radio control acft operating from arpt, CTAF monitored, overfly field to enter traffic pattern. Rwy 09-27 dsplcd thlds marked with green lgt atop yellow cone.

AIRPORT MANAGER: (740) 862-8422

COMMUNICATIONS: CTAF 122.9

BANNOCK HELIPORT (2D6) 0 N UTC-5(-4DT) N40°06.42' W80°58.52'

DETROIT

1100 NOTAM FILE CLE

HELIPAD H1: H20X20 (CONC)

HELIPORT REMARKS: Attended Mon-Fri 1300-2100Z.

AIRPORT MANAGER: 740-968-3504

COMMUNICATIONS: CTAF 122.9

® CLEVELAND CENTER APP/DEP CON 126.95 or call ZOB 440-774-0442

BARBER (See ALLIANCE on page 242)

BARNESVILLE-BRADFIELD (6G5) 1 NW UTC-5(-4DT) N40°00.15' W81°11.51'

DETROIT

1312 B NOTAM FILE CLE

RWY 09-27: H4003X65 (ASPH) S-30 MIRL

RWY 09: Thld dsplcd 299'. Road.

RWY 27: REIL. Trees.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 09-27; REIL Rwy 27; arpt beacon—CTAF.

AIRPORT REMARKS: Attended dalgt hrs. Birds and other wildlife on and invof arpt.

AIRPORT MANAGER: (740) 484-1971

COMMUNICATIONS: CTAF/UNICOM 123.0

® CLEVELAND CENTER APP/DEP CON 126.95 or call ZOB 440-774-0442

RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.

BELLAIRE (H) VOR/DME 117.1 AIR Chan 118 N40°01.02' W80°49.03' 274° 17.3 NM to fld. 1307/7W.

L-29B
IAP

