


WAAS CH <b>93601</b> <b>W20A</b>	APP CRS <b>206°</b>	Rwy Idg <b>4410</b> TDZE <b>955</b> Apt Elev <b>957</b>
--	------------------------	---

# RNAV (GPS) RWY 20

DAYTON-WRIGHT BROTHERS (MGY)



<p><b>▼</b> DME/DME RNP-0.3 NA. Inoperative table does not apply. If local altimeter setting not received, use James M Cox Dayton Intl and increase all DAs/MDAs 60 feet. Visibility reduction for helicopters NA. VDP NA when using James M Cox Dayton Intl altimeter setting.</p>	<p><b>MALS</b></p>	<p><b>MISSED APPROACH:</b> Climb to 3100 direct SOVVO and hold.</p>
---	--------------------	---

ASOS <b>118.375</b>	COLUMBUS APP CON <b>118.85 269.275</b>	CLNC DEL <b>119.4</b>	UNICOM <b>122.8 (CTAF) 0</b>
------------------------	---	--------------------------	---------------------------------



EC-2. 01 MAR 2018 to 29 MAR 2018

EC-2. 01 MAR 2018 to 29 MAR 2018



CATEGORY	A	B	C	D
LPV DA	1294-1 1/4 339 (400-1 1/4)			
LNAV MDA	1440-1	485 (500-1)	1440-1 1/2 485 (500-1 1/2)	1440-1 1/2 485 (500-1 1/2)
CIRCLING	1480-1 1/4	523 (600-1 1/4)	1520-1 1/2 563 (600-1 1/2)	1660-2 1/4 703 (800-2 1/4)